

# EarthResistance

Use the **KEW4105A** for single earth spike systems and the **KEW4200** for multi earth spike systems



Video link



KEW4105A	Three / two wire Earth Resistance tester	
KEW4200	TRMS Earth Resistance clamp meter	

# FuseFinder



## FUSEFINDER 2

Easily identify those circuits with the Fusefinder. Complete with mains lead.

Option: ACC016E test lead set for lighting circuits

